



# Assembly instruction: 34 A4


Series: 1.0/2.3 DIN 47297  
75 Ohm

Straight connector  
for flexible cable


Cable entry:  
Center contact - crimp  
Braid - crimp



1) Prepare the cable according to the diagram.



- 2) Slide ferrule "A" onto the cable.
- 3) Push center pin "B" on the inner conductor of the cable up to the dielectric and crimp it. \*)
- 4) Splay out the braid.



- 5) Insert the prepared cable into the connector body "C", until the center pin engages perceptibly. Ensure that the braid covers the knurled connector end.
- 6) Slide ferrule "A" over the braid up to the connector body and crimp as close to the connector body as possible. \*)

\*) For the crimping die part-nr. please consult the relevant customer drawing.

Für diese technische Unterlage behalten wir uns alle Rechte vor. (DIN 34)

				<b>Rosenberger</b>			
				Hochfrequenztechnik  CAD			
				84526 Tittmoning			
b	01-0451	28.09.01	Kra. Sa.	Bearb.	25.07.96	Krautenb. Sa.	M 2 : 1
a	CAD-MTP	25.07.96	Kra. Sa.	Gepr.	28.9.01	K.T.	Blatt 1/1
Zust.	Aenderung	Datum	Name				

<b>Tools:</b>	
Stripping tool	.....
Crimp tool 11 W 150-000	.....
	.....
	.....